



JON M. HUNTSMAN, JR.  
Governor

GARY R. HERBERT  
Lieutenant Governor

# State of Utah

## DEPARTMENT OF NATURAL RESOURCES

### Division of Oil, Gas & Mining

MICHAEL R. STYLER  
Executive Director

JOHN R. BAZA  
Division Director

### Inspection Report

#### Minerals Regulatory Program

Sept 05, 2007

Supervisor WRT

**Mine Name:** B & C Limestone Quarry  
**Operator Name:** Bryce Haas

**Permit number:** M/039/013  
**Inspection Date:** August 27, 2007  
**Time:** 1:30 pm

**Inspector(s):** Lynn Kunzler, DOGM

**Other Participants:** none

**Mine Status:** Active (undergoing reclamation)

#### Elements of Inspection

1. Permits, Revisions, Transfer, Bonds
2. Public Safety (shafts, adits, trash, signs, highwalls)
3. Protection of Drainages / Erosion Control
4. Deleterious Material
5. Roads (maintenance, surfacing, dust control, safety)
6. Concurrent Reclamation
7. Backfilling/Grading (trenches, pits, roads, highwalls,
8. Soils
9. Revegetation
10. Other

Evaluated	Comment	Enforcement
<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>

#### Purpose of Inspection:

Check progress of reclamation of this site.

#### Inspection Summary:

There has not been any significant change noted since my May, 25, 2007 inspection. I discussed the progress (or lack thereof) with Mr. Haas on August 29<sup>th</sup>. He indicated that he was aware of approaching deadlines, and had recently completed repairs on his equipment. He intended to continue the reclamation work within the next couple of days.

Reclamation tasks still remaining include: Removal of the old trackhoe, removal of stone from the 'meadow' area, regrading the waste piles around the pit area, plugging of the well (if SITLA requires), removal of the shop building, topsoil replacement, and seeding, (task #'s 2, 3b, 3c, 4, and 5 as outlined in the Division's December 6, 2006 letter).

Photos were taken to document site conditions.

#### Conclusions and Recommendations:

Continue to monitor this site when in the area.

**Inspector's Signature**

LK:pb

cc: John Blake, SITLA

O:\M039-Sanpete\M0390013-BandCLimestone\inspections\Insp-08272007.doc